



ILLINOIS TOLLWAY CHANGE ORDERS
August 2019

[I-18-4373 Additional Railroad Flagger Costs](#)

[I-18-4392 Signing Modifications](#)

[RR-13-4116 Emergency Patching](#)

[RR-18-4400 Hydroexcavate Plaza 23 Post Foundations](#)

[I-18-4392 IDOT Lighting Modifications](#)

[I-18-4392 IDOT Light Poles](#)

[I-18-4438 CM Field Office - Type C](#)

[RR-16-4285 EO6 Building Utilities - Water & Sewer](#)

[RR-18-4351 Field Issue #1](#)

[RR-18-4351 Temporary Impact Attenuator Repair](#)

[I-18-4390 Oasis Maintenance During Construction - Supplement](#)

[I-16-4274 Subgrade Soil Stabilization, Type IV Ramps D & E](#)

[I-18-4373 Barrier Wall Expansion Joints](#)

[I-18-4392 High Tension Cable Median Barrier](#)

[I-18-4695 Additional Excavation & Embankment for I-90 EB Eastside of Higgins Creek - Supplement #2](#)

[RR-16-4258 High-Speed Doors Access Control System](#)

[I-18-4374 Temporary IDOT Surveillance Cable at US RT 41](#)

[I-18-4392 IL 23 Resurface South Limits](#)

[I-18-4430 Drilled Shaft Elevation Discrepancy](#)

[RR-13-4116 Beam Replacement](#)

[RR-16-4277R Shoulder Reconstruction](#)

[RR-18-4439 Additional Maintenance of Traffic - TMA](#)

[RR-16-4256 Fiberglass Conduit](#)

[I-18-4392 Parking Lot Mods](#)

[I-18-4392 Plaza Loop Conduit](#)

[RR-13-4116 Ground Heater](#)

[I-17-4688 Furnish ALSF Equipment](#)

[RR-18-4404 Pad for Equipment Storage](#)



ILLINOIS TOLLWAY CHANGE ORDERS
August 2019

[I-17-4688 Quantity Adjustment - Ductbank Backfill](#)

[I-18-4374 IDOT Sewer Relocation at BN 361](#)

[I-18-4392 IL 23 Undercuts - North Lanes](#)

[I-18-4695 ITS Power Relocate - Supplement #2](#)

[RR-17-4313 Install New Lighting Cable Harness](#)

[RR-13-4116 CTS Patching](#)

[RR-13-4116 CTS Soil Modification](#)