



ILLINOIS TOLLWAY CHANGE ORDERS
June 2025

[RR-24-4976 Rapid Setting Latex Modified Concrete, Pavement Patching, Class A Ty II, 13in](#)

[I-21-4732 Test Pile Pre-core](#)

[RR-24-4976 Rapid Setting Latex Modified Concrete Pavement Patching Class A Ty IV, 12in](#)

[RR-24-4976 I-90 Asphalt Joint Repair](#)

[I-17-4673 Labor and Material Costs](#)

[I-20-4533 2025 Additional Costs](#)

[I-17-4673 Plaza 306 Underground](#)